Ref	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	49002	"451"/\$.ccls.	USPAT	OR	ON	2005/03/03 15:10
L2	347	"451"/\$.ccls. and sample and resin	USPAT	OR	ON	2005/03/03 15:21
L3	33	("20010036676" "20020127950" "20020173225" "20030153245" "5558568" "5605706" "5762536" "5916012" "6025015" "6066030" "6146248" "6204922" "6241583" "6241585" "6244935" "6248000" "6261959" "6271047" "6302767" "6322427" "6383332" "6406363" "6447369" "6475070" "6514775" "6517413" "6607422" "6609947" "6620031" "6629874" "6664557" "6670200" "6673637").PN.	US-PGPUB; USPAT; USOCR	OR .	OFF	2005/03/03 15:11
L4	1870451	"451"/\$.ccls. and sample and resin and reference (point or mark)	USPAT	OR	ON	2005/03/03 15:22
L5	9	"451"/\$.ccls. and sample and resin and reference adj (point or mark)	USPAT	OR	ON	2005/03/03 15:22
L6	159	("5741171" "5816899" "5948203" "59 64643" "6071177" "6208425" "621304 4" "6213844")".PN" and resin	USPAT	OR	OFF	2005/03/03 15:26
L7	159	("5741171" "5816899" "5948203" "59 64643" "6071177" "6208425" "621304 4" "6213844")".PN" and resin and data	USPAT	OR	OFF	2005/03/03 15:29
L8	159	("5741171" "5816899" "5948203" "59 64643" "6071177" "6208425" "621304 4" "6213844")".PN" and resin and data and measure	USPAT	OR	OFF	2005/03/03 16:20
L10	1280	451/8	USPAT	OR	OFF	2005/03/03 16:21
L11	509	451/8 and measure	USPAT	OR	OFF	2005/03/03 16:21
L12	81	451/8 and measure and laser and computer	USPAT	OR	OFF	2005/03/03 16:42
L13	45	451/9 and measure and laser and computer	USPAT	OR	OFF	2005/03/03 16:43
L14	770	451/10	USPAT	OR	OFF	2005/03/03 16:51
L15	1786	451/28	USPAT	OR	OFF	2005/03/03 17:16
L16	4089	451/41	USPAT	OR	OFF	2005/03/03 17:16
L17	1803	451/41 and measure\$	USPAT	OR	OFF	2005/03/03 17:17
L18	1892	451/41 and measur\$	USPAT	OR	OFF	2005/03/03 17:17
L19	1482	451/41 and measur\$ and (wafer or sample)	USPAT	OR	OFF	2005/03/03 17:56
L20	654	451/285 and measur\$ and (wafer or sample)	USPAT	OR	OFF	2005/03/03 18:03
L21	821	451/287 and measur\$ and (wafer or sample)	USPAT	OR	OFF	2005/03/03 18:15

L22	711	451/288 and measur\$ and (wafer or sample)	USPAT	OR	OFF	2005/03/03 18:17
L23	367	451/289 and measur\$ and (wafer or sample)	USPAT	OR	OFF	2005/03/03 18:17
S34	159	("5741171" "5816899" "5948203" "59 64643" "6071177" "6208425" "621304 4" "6213844")".PN"	USPAT	OR	OFF	2005/03/03 15:25
S35	1	"6439979"	USPAT	OR	OFF	2005/03/01 22:14
S36	49002	"451"/\$.ccls.	USPAT	OR	OFF	2005/03/01 22:14
S37	17309	"451"/\$.ccls. and (polishing or grinding)	USPAT	OR	OFF	2005/03/01 22:15
S38	296	"451"/\$.ccls. and (polishing or grinding) and computer and laser	USPAT	OR	ON	2005/03/01 22:15
S39	216	"451"/\$.ccls. and (polishing or grinding) and computer and laser and (measure or measurement)	USPAT	OR	ON	2005/03/02 14:29
S40	202	"451"/\$.ccls. and (polishing or grinding) and computer and laser and (measure or measurement) and reference	UȘPAT	OR	ON	2005/03/02 16:53
S41	24	"451"/\$.ccls. and (polishing or grinding) and computer and laser and (measure or measurement) and reference adj (line or point)	USPAT	OR .	ON	2005/03/02 17:09
S42	2	"451"/\$.ccls. and (polishing or grinding) and computer and laser and (measure or measurement) and reference adj (line or point) and laser adj displacement	USPAT	OR	ON	2005/03/03 15:10